

## Studentovy koeficienty

počet stupňů volnosti  $n = N - 1$ , kde  $N$  je počet měření

$n$	hladina spolehlivosti				
	0,5000	0,6827	0,9000	0,9545	0,9973
1	1,000	1,837	6,314	13,96	235,8
2	0,817	1,321	2,920	4,526	19,21
3	0,765	1,197	2,353	3,307	9,219
4	0,741	1,141	2,132	2,869	6,620
5	0,727	1,110	2,015	2,649	5,507
6	0,718	1,091	1,943	2,516	4,904
7	0,711	1,077	1,895	2,429	4,530
8	0,706	1,067	1,860	2,366	4,277
9	0,703	1,059	1,833	2,320	4,094
10	0,700	1,053	1,812	2,284	3,957
11	0,697	1,048	1,796	2,255	3,850
12	0,695	1,043	1,782	2,231	3,764
13	0,693	1,040	1,771	2,212	3,694
14	0,692	1,037	1,761	2,195	3,636
15	0,691	1,034	1,753	2,182	3,586
16	0,690	1,032	1,746	2,169	3,544
17	0,689	1,030	1,740	2,158	3,508
18	0,688	1,028	1,734	2,149	3,475
19	0,688	1,027	1,729	2,141	3,447
20	0,687	1,026	1,725	2,133	3,422
25	0,684	1,021	1,708	2,105	3,329
30	0,683	1,017	1,697	2,087	3,270
40	0,681	1,013	1,684	2,064	3,199
50	0,679	1,010	1,676	2,051	3,157
70	0,678	1,007	1,667	2,036	3,111
100	0,677	1,005	1,660	2,025	3,077
200	0,676	1,003	1,653	2,013	3,040
$\infty$	0,675	1,000	1,645	2,000	3,000